



Steel Scraper Blade



1

Even minor scratches and base damage can have an enormously detrimental effect on ski performance. You can easily repair minor base damage yourself after cross-country skiing, downhill skiing or boarding using the two following techniques.

REPAIR CANDLE

ill. 1) Remove any remaining damaged base material using the steel scraper.

ill. 2) Light the repair candle.

Drip the liquid repair material onto the damaged spot and allow it to cool completely.

Tip:
Support the transparent candle on the steel scraper blade. The flame burns blue without sooty smoke.

ill. 3) Remove any excess material layer by layer, using the radial file or steel scraper.

Tip:
Make a small hole in the Base Tex and wrap it around the radial file. This will protect the base against scratches. (Align the hole in the Base Tex with the side of the base).

ill. 4) Brush out the base with a copper brush.

Repair Candle transparent



Repair Candle graphite



2

Base Tex




2

Base File Radial




3

Base Brush Copper



4

Base Brush oval Copper with strap



Även små repor och skador på belaget stör utrustningens åkeegenskaper enormt. Mindre skador på belaget repareras enkelt efter skidåkning/snowboardåkning med hjälp av de båda följande teknikerna.

REPAIR CANDLE

bild 1) Ta bort överskjutande skadat belagmaterial med hjälp av en stålsickel.

bild 2) Tändning av Repair Candle.

Låt den flytande reparationsmassan droppa ner på skadan och låt kallna helt.

Tips:
Håll det genomskinliga ljuset mot stålsickeln. Lågan är blå och sotar inte.

bild 3) Ta bort överflödigt material med radialfilen eller en stålsickel skikt för skikt.

Tips:
Ett litet hål i Base Tex och lindat runt radialfilen skyddar belaget mot repor. (Rikta in hålet i Base Tex mot belagsidan.)

bild 4) Borsta noggrant hela belaget med kopparborsten.

Selv små riper og skader på sålen påvirker skienes/snowboardets kjøreegenskaper voldsomt. Mindre skader etter skituren/brettkjøringen kan du lett reparere selv ved hjelp av følgende to teknikker.

REPAIR CANDLE

bilde 1) Fjern utstikkende deler av det skadde sålematerialet med stålsiklingen.

bilde 2) Tenning av Repair Candle.

Drypp den flytende reparasjonsmassen på det skadede stedet og vent til det er blitt helt kaldt.

Tips:
Hold Repair Candle mot metallsiklingen. Blå flamme som brenner uten røyk.

bilde 3) Fjern overflødig materiale med radialfilen eller stålsiklingen lagvis.

Tips:
Lag et lite hull i Base Tex og vikle den rundt radialfilen. Dette beskytter sålen mot riper. (Juster hullet i Base Tex med siden på sålen).

bilde 4) Borst godt over hele sålen med kobberborsten.



We recommend:
Well-aired room
Vi anbefaler:
Godt ventilert rom



We recommend:
Wear protective gloves
Vi anbefaler:
Bruk vernehansker



We recommend:
Wear respiratory mask (full/half face mask with gas filter Protection Level A2)
Vi anbefaler:
Bær andningsmask (hel-/halv skyddsmask med gasfilter beskyttelsesnivå A2)
Vi anbefaler:
Bruk åndedrettsvern (hel/halv vernemaske med gassfilter beskyttelsesnivå A2)